Qty:

06-01-11

06-01-11

Ob-01-11

1 Um:

Each

: BASKET BASE ASSEMBLY (350)

: D2221

: N/A

:NIA

: 1/20/2006

D

DD

B

: D2221 REV F



Date:

Wednesday, 12/14/2005 4:02:31 PM

User:

Kim Johnston

**Process Sheet** 

**Drawing Name** 

Part Number

Material Due Date

**Drawing Number** 

**Project Number** 

**Drawing Revision** 

Customer

: CU-DAR001 Dart Helicopters Services

**Job Number Estimate Number**  : 25233C

: 10189

P.O. Number

Prsht Rev.

:NIA

: 12/14/2005 This Issue

First Issue : 25232C **Previous Run** 

: NC : NIA

S.O. No. : N/A

Type

: LARGE FAB ASSY

SEE COMMENT BIELOW SEE COMMENT

Checked & Approved By

Comment

Written By

: Est Rev:J 05.09.02 Added D3442-1KJ/JLM

**Additional Product** 

Job Number:



Seq. #:

2.0

3.0

**Machine Or Operation:** 

Description:

D31661 1.0

Basket Hoop

4.0000 Each(s)/Unit

Comment: Qty.:

Pick:

Total:

4.0000 Each(s)

**Qty Part Number** 

Description Batch

4 D3166-1 RIB

<u>Basa49</u>

D22323

Basket Hinge

Comment: Qty.:

2.0000 Each(s)/Unit Total: 2.0000 Each(s)

Pick:

**Qty Part Number** 

Description Batch

2 D2232-3 Hinge bracket 624527

Support Gusset (350 Bask



Comment: Qty.: 4.0000 Each(s)/Unit

Total:

4.0000 Each(s)

Pick:

D2325

Description

**Qty Part Number** 

Support Gusset

Batch

4 D2325

B24529

4.0

D23273

Spacer Bushing

Comment: Qty.:

2.0000 Each(s)/Unit Total: 2.0000 Each(s)

Pick:

**Qty Part Number** 

Description Batch

2 D2327-3 Bushing

B24530

Ø 06-01-1

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES	WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	Δ:	Date:			

Part No:	PAR #: Fault Category:	NCR: Yes No DQA:	Date:
		QA: N/C Closed:	Date:
	WORK ORDER NON-CONEC	ODMANCE (NCD)	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B		Verification	A					
DATE	STEP	Section A	Initial Chief Eng	Action Description Sign &		Section C	Approval Chief Eng	Approval QC Inspector				
<b></b>												
							· · · · · · · · · · · · · · · · · · ·					
				340								

NOTE: Date & initial all entries

Date: Wednesday, 12/14/2005 4:02:31 PM User: Kim Johnston **Process Sheet** Drawing Name: BASKET BASE ASSEMBLY (350) Customer: CU-DAR001 Dart Helicopters Services Job Number: 25233C Part Number: D2221 Job Number: Seq. #: **Machine Or Operation:** Description: Mounting Bracket D2581 5.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description Batch B Mounting Bracket \$23580 06-01-11 2 D2581 D34421 6.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description Batch B23544 2 D3442-1 Shim W 06-01-11 7.0 M304EX07516F Expanded Metal Flat Stai Comment: Qty.: 37.8000 sf(s)/Unit Total: 37.8000 sf(s) Pick: **Qty Part Number** Description Batch DD MIGING 36 sf M304EX0.75-16F Expanded Metal 06-01-11 8.0 M304TS0750W065 304 SQ Tube.75x.75x.065W Comment: Qty.: 29.4000 f(s)/Unit Total: 29.4000 f(s) Pick: 3/4" x 3/4" x 0.063 wall 304/316 SStubing Batch: MIQUU) 06-111-11 LARGE FABRICATION RESOURCE 1 9.0 LARGE FAB 1 Comment: LARGE FABRICATION RESOURCE 1 1-Cut D2235-1 Rib from D3166-1 Rib As Per Dwg D2235 2-Drill hole in D2221-3 as per Dwg D2221 3-Deburr 4-Remove all markings on material before welding 5-Weld as per Dwg D2221 using Welding Table and corner JigDeburr as required DD

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES							
DATE	STEP	EP PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		`		100					
Part No	):	PAR #:	Fault Category:	·	NCR: Yes	No DQ	A:	Date: _	

QA: N/C Closed: \_\_\_\_ Date: \_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B	Verification		Τ				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			
				ė							
		1									

NOTE: Date & initial all entries

Wednesday, 12/14/2005 4:02:31 PM Date: Kim Johnston User: **Process Sheet** Drawing Name: BASKET BASE ASSEMBLY (350) Customer: CU-DAR001 Dart Helicopters Services Job Number: 25233C Part Number: D2221 Job Number: Seq. #: Description: **Machine Or Operation:** QC9/6 DDIMENSIONAL & WELDING INSPECTION 10.0 Comment: DDIMENSIONAL & WELDING INSPECTION 11.0 POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION 12.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION HAND FINISHING RESOURCE #1 13.0 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 Seal support gusset seam with white sikaflex-291 Batch: <u>M1913 Y</u> SAP Expiry date: <u>06106</u>20 06:01 117 DOCUMENT CONTROL 14.0 Comment: DOCUMENT CONTROL D 00/01/19 Inspection Level 21 U 06-01.19 Job Completion

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	By Date		Approval Chief Eng / Prod Mgr	Approva QC Inspect
		•					
					<u> </u>		
Part No	:	PAR #: Fault Category: NC	R: Yes	No DQ	A:	_ Date: _	
			QA:	N/C Close	d:	Date:	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Verification		Approval		
DATE	STEP	Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
				÷						
						,				
				-						
<del></del>										

NOTE: Date & initial all entries




BW PH			DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA		
CHEC	KED	APPROVED AN	DRAWING NO.	REV.	F
	#	M	D2221 SHEET	1 OF	3
DATE			TITLE	SCAL	E
05.0	6.07		BASKET BASE ASSEMBLY (350)	NT	s
O		95.11.21	SEPARATE BASKET AND LID		
D		96.06.21	CHANGE LATCH		
Ε		01.04.19	CHANGE HINGE		
F		05.06.07	ADD SHIM UNDER HINGES,		

ADD HOLES FOR SPLIT LID BASKETS

RELEASED

PARTS LIST FOR D2221 BASKET BASE ASSEMBLY

PART NO	QUANTITY	LENGTH	LENGTH	DESCRIPTION
·		Α	В	
D2221-1	2		96.00	RIB
D2221-3	2		25.50	RIB
D2221-5	2	18.88		RIB
D2221-7	1	55.25		RIB
D2232-3	2	N/A	N/A	HINGE PLATE
D2235-1	4	N/A	N/A	RIB
D2325	4	N/A	N/A	SUPPORT GUSSET
D2327-3	2	N/A	N/A	BUSHING
D2581	2	N/A	N/A	MTG BRKT
D3442-1	2	N/A	N/A	SHIM




D2221-1/-3/-5/-7

- 1) CUT LENGTH/SHAPE PER DIAGRAM AND PARTS LIST
- 2) MATERIAL: AISI 304/316 SS, 3/4 X 3/4 X 0.060 WALL SQUARE TUBING (REF. DART SPEC M304TS0.750W.060)
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) DRILL Ø0.257 HOLES ONLY WHEN ASSEMBLING D2221 BASE WITH D2989-041/-043 BASKET LID


Copyright @ 1994 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.






DESIGN BW	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED	APPROVED A	DRAWING NO.	REV. F
#	#	D2221 SHEET	3 OF 3
DATE		TITLE	SCALE
05.06.07		BASKET BASE ASSEMBLY (350)	1:8



## SECTION A-A SAME BOTH END RIBS



SECTION B-B SAME BOTH CENTER RIBS

Copyright © 1994 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.